



## North Fork Indian Creek

### Log Barrier Removal



Follow-up debris removal was conducted during the fall of 1985 and the spring of 1986 on a site previously worked on during the summer of 1984 under contract C-455.

The worksite in Section 36, T14N R13W of the Boonville quadrangle is located on the property of Lloyd Huss, 911 High Lane, Redondo Beach, CA 90278.

Additional logs and debris exposed by the flushing of impounded bedload during the winter 84/85 was removed and burned.

Removal of the material at this site will allow additional flushing of impounded bedload during the winter 86/87. Adequate passage for steelhead should now exist through this site. The suitability of passage for salmon will depend upon the degree of downcutting that the channel is able to achieve during the winter flows.

An inspection of the site will be needed in 1987 to determine if the configuration of the channel and debris is adequate for fish passage.



CONTOUR INTERVAL 80 FEET  
DATUM IS MEAN SEA LEVEL

ROAD CLASSIFICATION  
 Medium duty ——— Light duty ———  
 Unimproved dirt - - - - -  
 State Route - - - - -



QUADRANGLE LOCATION

BOONVILLE, CALIF.  
 1:62,500

HOPLAND 1961